

File E359349 Vol 1 Authorization Page 1 Issued: 2013-05-22

Revised: 2023-11-27

# FOLLOW-UP SERVICE PROCEDURE (TYPE R)

PHOTOVOLTAIC MODULES AND PANELS WITH SYSTEM VOLTAGE RATINGS OVER 600 VOLTS (QIIA, QIIA7)

Manufacturer:	SEE ADDENDUM FOR MANUFACTURER LOCATIONS
Applicant: (100571-342)	580558 (Party Site) Suzhou Talesun Solar Technologies Co Ltd Changkun Industrial Park 1 Talesun Road Shajiabang Town CHANGSHU JIANGSU 215542 CN
Listee/Classified Company: (100571-342)	580558 (Party Site) SAME AS APPLICANT

## Use of the Mark

This Follow-Up Service Procedure authorizes the above Manufacturer(s) to use the marking specified by UL LLC, or any authorized licensee of UL LLC, including the UL Contracting Party, only on products when constructed, tested and found to be in compliance with the requirements of this Follow-Up Service Procedure and in accordance with the terms of the applicable service agreement with UL Contracting Party. The UL Contracting Party for Follow-Up Services is listed in the addendum to this Follow-Up Service Procedure ("UL Contracting Party"). UL Contracting Party and UL LLC are referred to jointly herein as "UL."

It is the responsibility of the Applicant, Manufacturer(s), and Listee/Classified Company to make sure that only the products meeting the aforementioned requirements bear the authorized Marks of UL LLC, or any authorized licensee of UL LLC.

## Additional Responsibilities

Additional responsibilities, duties and requirements for the Applicant and Manufacturers are defined under Additional Resources at the following website: <a href="https://www.ul.com/fus">https://www.ul.com/fus</a>.

Manufacturers without Internet access may obtain the current version of these documents from their local UL customer service representative or UL field representative. For assistance, or to obtain a paper copy of these documents or the Follow-Up Service Terms referenced below, please contact UL's Customer Service at <a href="https://www.ul.com/aboutul/locations/">https://www.ul.com/aboutul/locations/</a>, select a location and enter your request, or call the number listed for that location.

## Acceptance of Follow-Up Services

The Applicant and the specified Manufacturer(s) and any Listee/Classified Company in this Follow-Up Service Procedure must agree to receive Follow-Up Services from UL Contracting Party. If your applicable service agreement is a Global Services Agreement ("GSA"), the Applicant, the specified Manufacturer(s), and any Listee/Classified Company will be bound to a Service Agreement for Follow-Up Services upon the earliest by any Subscriber of a) use of the prescribed UL Mark, b) acceptance of the factory inspection, or c) payment of the Follow-Up Service fees. The Service Agreement incorporates such GSA, this Follow-Up Service Procedure and the Follow-Up Service Terms which can be accessed by clicking the following link: <a href="https://www.ul.com/resources/contracts/follow-up-service-terms">https://www.ul.com/resources/contracts/follow-up-service-terms</a>. In all other events, Follow-Up Services will be governed by and incorporate the terms of your applicable service agreement and this Follow-Up Service Procedure.

# Use and Ownership of the Follow-Up Service Procedure

This Follow-Up Service Procedure, and any subsequent revisions, is the property of UL and is not transferable. This Follow-Up Service Procedure contains confidential information for use only by the Applicant, the specified Manufacturer(s), and representatives of UL and is not to be used for any other purpose. It is provided to the Subscribers with the understanding

Authorization Page 2

that it is not to be copied, either wholly or in part unless specifically allowed, and that it will be returned to UL, upon request.

Issued: 2013-05-22

Revised: 2023-11-27

#### Definition of Terms

Capitalized terms used but not defined herein have the meanings set forth in the GSA and the applicable Service Terms or any other applicable UL service agreement.

## No Third Party Liability

UL shall not incur any obligation or liability for any loss, expense or damages, including incidental, consequential or punitive damages arising out of or in connection with the use or reliance upon this Follow-Up Service Procedure to anyone other than the above Manufacturer(s) as provided in the agreement between UL LLC or an authorized licensee of UL LLC, including UL Contracting Party, and the Manufacturer(s).

# Certification Body

UL LLC has signed below solely in its capacity as the certification body to indicate that this Follow-Up Service Procedure fulfills the requirements for certification documentation issued by the certification body. The certification body's accreditation status for the applicable certification scheme and identification of the accreditation body can be found at https://www.ul.com/resources/accreditation.

Deborah Jennings-Conner VP Regulatory Services UL LLC

File E359349 Vol 1 Addendum To Page 1 Issued: 2013-05-22 Authorization Page Revised: 2023-11-27

LOCATION

580558 (Party Site)

(100571-342) Suzhou Talesun Solar Technologies Co Ltd

Changkun Industrial Park

1 Talesun Road Shajiabang Town

CHANGSHU JIANGSU 215542 CN

Factory ID: A

UL Contracting Party for above site is: UL GmbH

1481899 (Party Site)

Talesun Technologies (Thailand) Co Ltd 7/473 Moo.6 Amatacity Mabyangporn Pluakdeang

Rayong 21140 TH

Factory ID: B01

UL Contracting Party for above site is: UL GmbH

2611010 (Party Site)

Sunshine Electrical Energy Co., Ltd

32/2 Moo 7, Bangsaothong Sub-District, Bangsaothong District, Samut Prakarn

Thailand 10570

Samut Prakarn 10570 TH

Factory ID: F06

UL Contracting Party for above site is: UL GmbH

2571911 (Party Site)
MECEN SOLAR VINA CO.,LTD

LOT CN2-2 AND CN9-4, YEN PHONG INDUSTRIAL PARK (EXPANDED AREA)

YEN TRUNG COMMUNE, YEN PHONG DISTRICT

YEN PHONG BAC NINH 16000 VN

Factory ID: MECEN

UL Contracting Party for above site is: UL GmbH

2503870 (Party Site)

SHENGTIAN NEW ENERGY VINA CO., LTD

Workshop A3a4, Phu Thai Industrial, Phu Thai Town, Kim Thanh District

Hai Duong Vietnam Hai Duong VN

Factory ID: ST01

UL Contracting Party for above site is: UL GmbH

3080081 (Party Site) ARTSOLAR(PTY)LTD

Gate 3,124 Escom Road New Germany, Unit 11, New Germany

Pinetown 3610 ZA

Factory ID: AS01

UL Contracting Party for above site is: UL GmbH

3141990 (Party Site) PT Apollo Solar Indonesia

Jalan Wiraraja Industrial Estate Building Block B No.7-8 Kabil Nongsa Kota

Batam

Kepulauan Riau 29467 ID

Factory ID: APOLLO

UL Contracting Party for above site is: UL GmbH

3179071 (Party Site) Ocean Energy Co., Ltd.

998/106-109 Moo 9, Bang Pla Subdistrict, Bang. Phli District,

File E359349 Vol 1 Addendum To Page 2 Issued: 2013-05-22 Authorization Page Revised: 2023-11-27

Samut Prakan Province 10540 TH

Factory ID: Ocean 01

UL Contracting Party for above site is: UL GmbH

2885896 (Party Site)

SOLAR LONG PV-TECH(CAMBODIA)CO.,LTD

A-03-02 at SIHANOUKVILLE S E Z PHUM POU THOEUNG

BET TRANG COMMUNE & PHUM SMACH DENG REAM COMMUNE PREY NOB DISTRICT

Preah Sihanouk 180101 KH

Factory ID: Solar long 01

UL Contracting Party for above site is: UL GmbH

3359433 (Party Site)

MEM PANEL SOLAR ENERJI SANAYI VE TICARET A.S.

Organized Industrial Site 3, Street No: 4 Onikisubat

Kahramanmaras 46050 TR

Factory ID: MEM 01

UL Contracting Party for above site is: UL GmbH